COATED CART COVERS

When laundering is required,
the following instructions must be used.

WASHING: A slow speed machine must be used. The wash wheel is to be stopped for draining and refilling between each.

Operation Cycle	Water level	Time	Max. Water Temp	Supplies
1st Suds	High	5 Min	100° F	Neutral Soap & Alkali
2nd Suds	High	10 Min	100° F	Neutral Soap
1st Rinse	High	3 Min	100° F	Water
2nd Rinse	Low	3 Min	90° F	Sour to PH 5.0

DRY: Air dry. If machine drying is necessary, tumble dry without heat.

IRON: Do not put covers through flatwork ironers.

CAUTION: Washing or drying in excess of the above recommendations will reduce service life and performance of the product.
NOTE: *Hard to clean spots – use a soft sponge with a liquid household / vinyl cleaner. Do not use harsh cleaners or solvents.*
NOTE: The above instructions are those recommended by the international fabircare institute for commercial washroom procedure.