UNCOATED CART COVERS

When laundering is required,
the following instructions must be used.

WASHING: Use mild non-bleach detergent suitable for nylon / polyester fabrics and follow manufacturer's instructions. Water temperature not to exceed 160°F

DRY: Air dry. If machine drying is necessary, do not exceed 250°F maximum and a time duration of two minutes maximum.

IRON: Do not put covers through flatwork ironers.

CAUTION: Washing or drying in excess of the above recommendations will reduce service life and performance of the product.